

SHIPS CLASSIFICATION MALAYSIA

SCM CIRCULAR





QUALITY MATTERS

Issue No 08/2014

Issue Date

24 JUNE 2014

TITLE

IMO OBLIGATORY REQUIREMENT:

FIREFIGHTER'S OUTFIT SCABA ALARM AND EXPLOSION PROOF TWO-WAY RADIOTELEPHONE APPARATUS

(ENTERING INTO FORCE: 01-JULY-2014)

To All Owners and Managers of Malaysian Vessels,

1. This circular highlights on IMO obligatory requirements (as above mentioned) entering into force in 01 July 2014, under SOLAS Ch.III/Reg. 17-1, adopted at IMO MSC 91 and was previously notified through SCM Circular issue No: 04/2014.

#	Convention/		Date of force		Subject/ Items Required	Key Words
	Resolutions.	Regulation		Application/		
1-12-2		II-2/1.2.5 (New para.)		KL < 2012-07-01.	SOLAS Reg.II-2/1 para .2.4 is added which requires Low volume alarm on self-contained compressed air breathing apparatus(SCABA) for fire-fighter's outfit	SCABA, Low volume alarm
					fitted.	
1-16	SOLAS MSC.338(91)	II-2/10.10.1	2014-07-01 Deadline: 2019-07-01.	KL < 2012-07-01.	Para 10.1 is replaced with an added reference to the revised FSS Code (Ch.3/2.1.2.2) at sub para .1 and .2, on requirement for low volume alarm on the self-contained compressed air breathing apparatus.	SCABA, Low volume alarm
1-17		,		KL ≥ 2014-07-01.	New requirement for carriage of two-way portable radiotelephone apparatus of explosion proof or intrinsically safe type for firefighter's communication.	2-way portable radio, Explosion proof,
			Deadline: 2018-07-01		intuinsically sale type for mengriters communication.	Firefighter's comm.

2. The 2012 amendments to SOLAS Convention adopted by IMO Resolution MSC.338(91) and the Fire Safety Systems (FSS) Code adopted by IMO Resolution MSC.339(91) will enter into force on 1 July 2014, introducing revised and new requirements for fire-fighter's outfit breathing apparatus and two-way portable radiotelephone apparatuses, as follows:

A. Breathing Apparatus

a) Changes to SOLAS regulation II-2/10.10.1 in accordance with IMO Resolution MSC.338(91) and the FSS Code in accordance with IMO Resolution MSC.339(91) mean that: "Compressed air breathing apparatus shall be fitted with an audible alarm and a visual or other device which will alert the user before the volume of the air in the cylinder has been reduced to no less than 200 l."

This requirement applies to ships constructed (keel laid) on or after 1 July 2014. Ships constructed (keel laid) before 1 July 2014 must comply no later than 1 July 2019.

b) New SOLAS regulation II-2/15.2.2.6 in accordance with IMO Resolution MSC.338(91), relating to 'Onboard training and drills' requires that: "An onboard means of recharging breathing apparatus cylinders used during drills shall be provided or a suitable number of spare cylinders shall be carried on board to replace those used."

This requirement applies to all ships on or after 1 July 2014.

B. Two-Way Portable Radiotelephone Apparatus

New SOLAS regulation II-2/10.10.4 in accordance with IMO Resolution MSC.338(91) requires that: "For ships constructed on or after 1 July 2014, a minimum of two two-way portable radiotelephone apparatus for each fire party for fire-fighter's communication shall be carried on board. Those two-way portable radiotelephone apparatus shall be of an explosion-proof type or intrinsically safe. Ships constructed before 1 July 2014 shall comply with the requirements of this paragraph not later than the first safety equipment survey after 1 July 2018."

3. Owners and operators of new and existing ships should ensure that the fire fighters' outfits and two-way portable radiotelephone apparatus for fire party on their ships meet the requirements of SOLAS and the FSS Code and that any changes to the fire locker contents are shown on the ship's fire control plans, if included. Amendment to the fire plan should be endorsed by the attending surveyor.

For further information you may contact:

Ships Classification (Malaysia) Sdn. Bhd.

Wisma SCM, No. 2 & 3, Block 2, Presint Alami, Persiaran Akuatik, Seksyen 13, 40675 Shah Alam, Selangor Darul Ehsan, Malaysia.

Phone: (603) - 5513 8170

Fax: (603) - 5513 8086

Website: www.myscm.com.my

Email: infohq@myscm.com.my

Capt M.Prathaban H/P:012 2997278 Email: mprathaban@myscm.com.my
Marby Rohani H/P:012 6071147 Email: marby@myscm.com.my
Mohd Nor Sahat H/P:012 234 9521 Email: mdnor@myscm.com.my
Sosanto Yusup H/P:013 3841229 Email: sosanto@myscm.com.my